



NU Series 9.0.3.1 Hotfix v1 Release Notes

Available firmware : 9.0.3.1 (c57339e2b971fa4dc1c621b1c1fca78ef594ac97/3b785d54cc15fece5931b4fedda194c1afe44b25)

HASH

md5 : 2981d8dd70b61f634f3019f02585de8f

sha1 : c3ed7241a9f10936a72e63a7fe923a5fc1184187

sha256 : fe0c18be9ad2e1af498a47d703ddffdd0f0f14703abc3e2cddeb8f9c2970faca

Installation instruction

=====

- The system will not automatically reboot after the software update.



- Log info : 9.0.3.1 update hotfix v1

Upgrade Notes

[Configuration]

[Upgrade]

- Bug Fixes
 - ◆ Fixed an issue where [Firmware Message] > " Automatic Firmware Upgrade" could incorrectly display a failed status in the log even when the firmware upgrade was successful.
 - ◆ Fixed an issue where the **Confirm** button in the firmware upgrade confirmation dialog could appear outside the dialog window.
 - ◆ Fixed an issue where the firmware download could repeatedly fail under certain conditions.



[Signature Update]

- Bug Fixes
 - ◆ Fixed an issue where importing signature updates could fail under certain conditions.

[Cloud Management]

- Bug Fixes
 - ◆ Fixed an issue where users could not log in to the management interface through Eye Cloud under certain conditions.

[Services]

[DHCP]

- Bug Fixes



- ◆ Fixed an issue where pages could fail to load properly under certain conditions.

[DHCP Server]

- Bug Fixes
 - Fixed an issue where adding an "A" record in [Domain] > [Edit] could fail under certain conditions.

[Anti-Virus Engine]

- Bug Fixes
 - ◆ Fixed an issue where the [Kaspersky Engine] service could fail to operate under certain conditions.

[Sandstorm]

- Bug Fixes
 - ◆ Fixed an issue where signature updates could repeatedly fail under certain conditions.



[WAF]

[WAF]

- Bug Fixes
 - ◆ Fixed an issue where the query results for "URL" in [WAF Logs] could be incorrect.

[Status]

[Connection Status]

- Bug Fixes
 - ◆ Fixed an issue where the information in the "Name" field under [Online Members] could be incorrect.

[System Status]

- Bug Fixes



- ◆ Fixed an issue where traffic on VLAN interfaces could not be displayed properly in [Timely Flow].

[Others]

[Management Interface]

- Bug Fixes
 - ◆ Fixed an issue where the "Traffic Graph" on [Home] could not be displayed properly in the Chrome browser.
 - ◆ Fixed an issue where input was not properly filtered on certain interfaces, which could potentially pose security risks.